



Bloomquist Creek - Outlet of the Chisago Lakes, Lake Improvement District to the Sunrise River

Monitoring Years: 2008

Current Impairments: At this particular location there are no impairments, however, other water bodies within the watershed are impaired for various parameters such as: turbidity, excess phosphorus, and other nutrients.

Interesting Facts about Bloomquist Creek:

- Collects water from a large chain of lakes: South Center, North Center, North Lindstrom, South Lindstrom, Chisago, and Green Lakes
- Transparency tube readings are generally high (clear water) unless there is a major runoff event
- Water does not move quickly at this location
- Runoff from Center City, Lindstrom, and Chisago City also collects in this creek